

Approved For Release 2009/08/03 : CIA-RDP80T00246A007500670002-4

25X1

Page Denied

NAVY Review Completed

Approved For Release 2009/08/03 : CIA-RDP80T00246A007500670002-4

On far side of oil line is a long
transit shed. is still 25X1
incomplete - the roof is on, it seems,
only temporarily: rain drips through, etc.

These lines run above ground here, then go under
ground at a point just this side of wall, designator L.

✕ Fresh water, good drinking, poor pressure.
Faucet-type, 2 1/2" connection.
15-20'

wooden platform above pipes - steps at
end toward center of pier.

light poles - lighting termed "poor"

wooden guard house

NAVY Review Completed

concrete

light poles - lighting termed "poor"

wooden platform above pipes - steps at
end toward center of pier


ramp bent over pipes

✕ Fresh water, good drinking, poor pressure.
Faucet-type, 2 1/2" connection.

Vessel's berth -

25X1

Approved For Release 2009/08/03 : CIA-RDP80T00246A007500670002-4



Approved For Release 2009/08/03 : CIA-RDP80T00246A007500670002-4